

# General Environmental Incident Summary

**Incident:** 4022      **Date/Time Notice:** 2/18/2016      **DEM Incident No:**

**Responsible Party:** Unknown

**Date Incident:** 2/17/2016      **Time Incident:** 0030      **Duration:**

**County:** Stark      **Twp:** 140      **Rng:** 96      **Sec:** 33      **Qtr:**

**Lat:** 46.89792      **Long:** -102.79560      **Method:** Interpolation from map

**Location Description:** 529 Elks Drive, Dickinson, ND

**Submitted By:** Andy McDonald

**Affiliation:**

**Address:** 400 N Fourth St.

**City:** Bismarck

**State:** ND

**Zip:**

**Received By:**

**Contact Person:**

unknown

unknown, ND

**Distance Nearest Occupied Building:** 30 Feet

**Release Contained:** Yes

**Type of Incident:** Transformer hit by vehicle

**Description of Released Contaminant:** Mineral Oil (<2ppm PCB per nameplate on transformer)

**Volume Spilled:** 5.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

**Cause of Incident:**

A vehicle struck the transformer and fled the scene. The incident was reported to the Dickinson Police Department.

**Risk Evaluation:**

None.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

None, other than the contaminated rock and gravel that was removed from the site.

**Action Taken or Planned:**

The spill was isolated to 6' x 2' area and there was no free flowing liquid present when the crews arrived. The damaged transformer was removed from the site, along with 3-4" (depth) of contaminated gravel/rock. The pad was rinsed with a solvent and absorbent materials were collected upon completion of cleanup.

**Wastes Disposal Location:**

**Agencies Involved:** Local Law Enforcement

## ***Updates***

---

***Date:*** 2/19/2016    ***Status:*** Reviewed - Assigned to NDDoH Division

***Author:*** Souder, Taylor

***Updated Volume:***

***Notes:***

Assigned to Division of Waste Management.

---

***Date:*** 3/17/2016    ***Status:*** Inspection

***Author:*** Washek, Sandi

***Updated Volume:***                      5.00 gallons

***Notes:***

Arrived on site at 12:15 p.m. Weather was partly cloudy with wind out of the NW at 20 mph. Temperature was 21 degrees. The transformer is located next to a residential house. The area around the pad is gravel and appears clean of all stained material. The transformer box has been fixed. Pictures were taken. No additional inspections needed.